

2024

Inspection of Automatic Sprinkler System

ASIB



Inspection of Automatic Sprinkler System

East London Industrial Development
Zone - AE6 vacant

Complete

Client/Site Name

East London Industrial Development Zone - AE6 vacant

Billing Address

East London Industrial Development Zone SOC Ltd P O Box 5458 GREENFIELDS 5208

Attention:

Mteteleli Zantsi
Camagwini Ngxokolo-Nomatye

Document No

UNC.10602

Prepared by

Keith van Onselen

Conducted on

19.06.2024 08:49 SAST

Site Location

East London IDZ
EC
5201
South Africa)

Disclaimer

We have pleasure in attaching our inspector's report.

Whilst every care is taken in the preparation of the report which describes the conditions as found, such report is not a guarantee carrying responsibility for results and neither this Company nor any of its employees or agents shall be liable for any loss or damage of whatsoever nature and howsoever caused, (whether by actual or alleged negligence or otherwise), in any way arising out of the acts or omissions of the Company and/or its employees or agents aforesaid.

The report is based upon the visual inspection of the external condition of the equipment where accessible without having to provide scaffolding, ladders, staging, lighting and not requiring the removal or displacement of any temporary or permanent structure, fitting or fixture.

If there are any points arising on which you require clarification, kindly communicate with the undersigned. Assuring you of our best attention at all times.

Confidentiality

In order to maintain the integrity and credibility of the inspection processes and to protect the parties involved, it is understood that the inspectors will not divulge to unauthorized persons any information obtained during this inspection unless legally obligated to do so.

Yours faithfully,

THE AUTOMATIC SPRINKLER INSPECTION BUREAU (PTY) LIMITED

A handwritten signature in black ink, appearing to read 'Nico van Loggerenberg', written in a cursive style.

Nico van Loggerenberg
Managing Director

1. Report Summary

THE AUTOMATIC SPRINKLER INSPECTION BUREAU (PTY) LIMITED



REGISTRATION NUMBER: 1970/010833/07

1407 IMBALI
CNR LOUIS BOTHA AND
TUDHOPE AVENUES
BEREA
JOHANNESBURG
2198

TELEPHONE: +27 11 642 1703
FACSIMILE: +27 11 642 1019
E-MAIL: asib@asib.co.za
WEB SITE: www.asib.co.za

P O BOX 3139
HOUGHTON
2041

INDEPENDENT
THIRD PARTY
INSPECTION AND
ADVISORY
SERVICE SINCE
1970

© 1970 - 2024 AUTOMATIC SPRINKLER INSPECTION BUREAU ALL RIGHTS RESERVED

Code

B - Full Protection, Clearance
Certificate Issued

Please Note:

The Clearance Certificate is issued subject to the items in the report being attended to.

Standard

10th Edition

ASIB Contract No

UNC.10602

Client Order No

004203

Was the sprinkler system design in order

Yes

Was the water supplies in order

No

Refer to report UNC.9478 conducted on 08/05/2024

Was the pump room in order

Yes

Refer to report UNC.9478 conducted on 08/05/2024

Was the installation control valves in order

Yes

Refer to Installation Control Valves - Section 7.

Was the storage in order

Yes

Vacant building

2. Hand Fire Appliances

Hand Fire Appliances - One unit per 100 m² of floor area.

Clear access to the hand fire appliances must be maintained at all times.

3. Occupancy & Storage Guidance

Percentage Hazard.

% Ordinary Hazard	10 From 0 to 100
--------------------------	---------------------

% High Hazard	90 From 0 to 100
----------------------	---------------------

Stack height signs not less than 500 mm by 500 mm in size must be prominently displayed at the maximum level of the allowable storage height in all storage and process risk areas.

Occupancy / Process Risk

Occupancy/Risk

Occupancy/Risk 1

► **Ordinary Hazard / High Hazard**

High Hazard

► **Select Occupancy / Process Risk**

Storage Risk

Where goods of differing categories are stored within the same area, it is the stack height limitations of the goods with the highest category that will apply.

► **Product Stored**

Vacant building

Category

CAT I

Storage

4. Sprinkler System Design

Building

Building 1

Building Name

East London Industrial Development Zone - AE6 vacant

Date of First Inspection

2010

Original Installer

Fire Sprinkler Installations

Extension By

NA

Building Area m²

Approximately 2800

Height of Building in meters

11,5

Sprinkler Detail

Area

Area 1

► Area & Type of Sprinklers

Roof Sprinklers

Ceiling Sprinklers

Canopy Sprinklers

Number of Sprinklers

Approximately 400

Calculations

Hydraulic Calculations

Area of Operation

Area of Operation 1

► Area of Operation	Pump Duty
Flows & Pressures 7500 l/min @ 960 kPa	
Area of Operation 2	
► Area of Operation	Design Flow & Pressure
Flows & Pressures 3050 l/min @ 469 kPa	
Additional Sprinkler System Designs Required	No

5. Water Supplies

► Water Stored on Site.

Yes

Refer to report UNC.9478 conducted on 08/05/2024

Add Water Storage Tanks






6. Pump Room

Pump Installed on Site

Yes

Refer to report UNC.9478 conducted on 08/05/2024

Add Pump House

7. Installation Control Valve(s)	
7.1 Sprinkler control valves accessible	Yes
Valve Cabinet	
Valve Cabinet 1	
Location:	
South West corner	
<div>   </div> <div> <div>Photo 1</div> <div>Photo 2</div> </div>	
Number of Alarm Valves Installed	2
7.2 Sprinkler Valve Location Plate Installed	Yes
7.3 Fire Brigade Booster Pressure Limitation Plate	Yes
7.4 Block Plan Installed	Yes
7.4.1 Is the block plan labelled in accordance with the areas fed by the sprinkler control valve assemblies	Yes
7.4.2 Are the correct installation details recorded on the block plan	Yes
<div>    </div> <div> <div>Photo 3</div> <div>Photo 4</div> <div>Photo 5</div> </div>	
7.5 Sprinkler Valve Instruction Chart	Yes
7.6 Is a sprinkler spares box present	Yes
7.6.1 Was the spares box contents accessible	Yes
7.6.2 Are the spares quantities correct	Yes
7.7 By Pass Arrangement Installed	No

It is recommended a valve bypass assembly be provided at each installation control valve. This allows the alarm valve to be overhauled without isolating the system and prevents wastage of water.

7.8 Fire Brigade Booster Connections Installed Correctly and Accessible

No

Installations must be fitted with fire brigade booster connections which will enable the fire brigade to pump water into the installation using their own equipment.

It appears that the booster connection piping to the main distribution riser is too long, which may restrict the opening of the booster plunger into the main distribution riser, this will prevent effective boosting of the sprinkler system and must be revised.




Photo 6

7.9 Are the Installation Control Valves Housed within an Approved Valve Cabinet

Yes

Sprinkler protection is required within the valve cabinet



7.10 Flow Switch Installed Correctly

Yes

7.11 Manifold Correctly Supported

Yes

7.12 Riser Mains Correctly Supported

Yes

7.13 Riser Mains Externally Located

No

7.14 Flow Measuring Device Installed.

Yes




Photo 7




Photo 8

Flow Test Results

Pass

Recorded Flow and Pressure

3500 l/min @ 940 kPa

7.15 Correct Pressure Gauges Installed

Yes

7.16 Correct Gauge Cocks Installed	Yes
7.17 Flanges Short Bolted	Yes
The bolts for these flanges must be removed and replaced with the correctly sized bolts so as to ensure that at least two full thread pitches past the chamfer protrude beyond the nut.	
7.18 Loose / Missing Bolts, Nuts & Washers	No
7.19 False Alarm Prevention Pump Installed	N/A
7.20 Drain & Test Pipes Installed Correctly	Yes
7.21 Weekly tests of the installation control valves alarm bell must be carried out with the alarms sounding for at least thirty seconds.	
All water pressure gauge readings must be checked and recorded.	
The testing and records should be carried out by a member of staff delegated to do this.	
7.22 Trunk Main Pressure (kPa)	
1080	
7.23 Installation Pressure (kPa)	
1150	
7.24 ASIB Overhaul Date Tag No	Yes
Last Overhaul Date	
2022	
Next Overhaul Date	
2025	
7.25 Alarm Motor & Gong Test	Passed
7.26 Are All Valves in the Correct Positions	Yes
7.27 Are All Valves Secured	Yes
Non Compliance - Items	
Recommendation Items	

8. Storage

No storage was taking place at the time of inspection.



9. Sprinkler System

Sprinkler System

Area

Area 1

Specified Area.

Warehouse

System Issue

Issue

Issue 1

Finding

Pipe Support

The sprinkler pipe work must be correctly supported.



Belt-to-belt hangers utilized.



Belt-to-belt hangers must be removed and the pipe work correctly supported.

Location of Finding.

Main feed
Distribution main




Photo 9




Photo 10




Photo 11




Photo 12




Photo 13




Photo 14

10. Proof of Inspection

Proof of inspection.

For and on behalf of client:



Camagwini Ngxokolo-Nomatye
20.06.2024 12:26 SAST

Proof of inspection.

ASIB Inspector:



Keith van Onselen
20.06.2024 12:27 SAST

WARNING

© The Automatic Sprinkler Inspection Bureau (Pty) Ltd 1970-2024 All rights reserved.

Copyright subsists in this work. All information contained in this report is the property of The Automatic Sprinkler Inspection Bureau (Pty) Ltd. No part of this report may be reproduced, published, performed, broadcast, transmitted or adapted in any form or by any electronic, mechanical or other means without the written permission of the copyright holder. Any unauthorised reproduction, publishing, performance, broadcasting, transmission or adaption of this work will constitute copyright infringement and render the doer liable under both civil and criminal law.

The primary function of the ASIB is to protect the interests of the end user and as a result, we constantly update the list of registered suppliers and installing companies.

These companies have proven that they are capable of installing, extending and servicing fire sprinkler systems to the correct standards.

We have had occasion to remove companies for valid reasons which are not confidential and include, but are not limited to, poor workmanship, design, fabrication, incorrect advice, lack of skilled staff, fraudulent quotations and financial instability.

It is important to note that if a company is not listed with the ASIB and carries out work on a sprinkler system we will not be in a position to issue a Clearance Certificate for the premises which, in turn, may place you at risk.

In selecting your service provider, it is important to appreciate that the ASIB is not seeking to infer that a non-listed service provider is necessarily not capable of offering the required service to an appropriate standard. What the ASIB is saying, is that the ASIB is not in a position to give you the assurance that a non-listed provider concerned has demonstrated that it complies with the ASIB standards. In addition, because the ASIB is unable to fully inspect an installation (which by its nature has many inaccessible components), you will appreciate that the ASIB is also unfortunately not in a position to issue a Clearance Certificate in relation to an installation done by a non-listed company.

We advise you to check the listing status of the service provider you choose especially if there is any uncertainty.

You can access our website at <http://www.asib.co.za> which is current or phone our offices at 011 642 1703 for verification.

Email:

Email: 1

Recipient

Mteteleli@elidz.co.za

Email: 2

Recipient

camagwini@elidz.co.za

Media summary



Photo 1



Photo 2




Photo 3



Photo 4




Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14